

Message

From: Smallbeck, Donald R. [Donald.Smallbeck@amecfw.com]
Sent: 10/27/2016 3:02:38 PM
To: Davis, Eva [Davis.Eva@epa.gov]
CC: d'Almeida, Carolyn K. [dAlmeida.Carolyn@epa.gov]; Wayne Miller [Miller.Wayne@azdeq.gov]; JERRARD, CATHERINE V CIV USAF HAF AFCEC/CIBW [catherine.jerrard@us.af.mil]
Subject: RE: redrilling of well UWBZ34
Attachments: Log from UWBZ34.pdf - Adobe Acrobat Pro.pdf

Eva

UWBZ 34 was over-drilled because as grout was tremied into the annular space, a hot spot developed which resulted in the PVC casing becoming deformed inward by the heat thus causing a restriction of the interior diameter of the casing at 21 feet below ground surface. Because the interior constriction of the casing diameter rendered the well unusable, the casing, grout, and filter pack material were removed and replaced. UWBZ34 was over-drilled in the same location as the original boring. Over-drilling is done with a rig that so that all of the previous casing, filter pack and grout can be pulled out. A clean boring hole remains in which to reinstall a new casing and fresh annular materials. The revised boring log (attached) which is the same as the original except for the date range which includes the time period for the removal and replacement of the shallow portion (21 feet) of the well with the interior restriction.

D.R. Smallbeck
Principal Program Manager
Construction Remediation




Amec Foster Wheeler
4600 E Washington Street, Suite 600
Phoenix, Arizona 85034
Tel: 602-733-6040
Cell: 707-480-7212
Donald.Smallbeck@amecfw.com
amecfw.com

From: Davis, Eva [mailto:Davis.Eva@epa.gov]
Sent: Friday, October 07, 2016 1:19 PM
To: Smallbeck, Donald R.
Cc: d'Almeida, Carolyn K.; Wayne Miller; JERRARD, CATHERINE V CIV USAF HAF AFCEC/CIBW
Subject: redrilling of well UWBZ34

Don – as I have been reviewing Williams data lately, I noticed again that the July 8 weekly report states that well UWBZ34 was re-drilled. I don't remember this ever being discussed during one of our meetings or calls, what was the reason for re-drilling it? Where was it located relative to the original well? Could you please provide the drilling log for this new well – thanks Eva



This message is the property of Amec Foster Wheeler plc and/or its subsidiaries and/or affiliates and is intended only for the named recipient(s). Its contents (including any attachments) may be confidential, legally privileged or otherwise protected from disclosure by law. Unauthorised use, copying, distribution or disclosure of any of it may be unlawful and is strictly prohibited. We assume no responsibility to persons other than the intended named recipient(s) and do not accept liability for any errors or omissions which are a result of email transmission. If you have received this message in error, please notify us immediately by reply email to the sender and confirm that the original message and any attachments and copies have been destroyed and deleted from your system. This disclaimer applies to any and all messages originating from us and set out above. If you do not wish to receive future unsolicited commercial

electronic messages from us, **please forward this email to: unsubscribe**  **@**  **amecfw.**  **com and include**
“Unsubscribe” in the subject line. If applicable, you will continue to receive invoices, project communications and similar factual, non-commercial electronic communications.

Please click <http://amecfw.com/email-disclaimer> for notices and company information in relation to emails originating in the UK, Italy or France.